



PROGRAM ADMINISTRATOR
 DEPARTMENT ALECP
 INTERTEK
 3933 U.S. ROUTE 11
 CORTLAND, NY 13045-0950

REVISION DATE: May 14, 2014

ORIGINAL ISSUE DATE: March 3, 2014

Recertification due: March 2016

An Activity Sponsored and Administered by
 Intertek

AGM Guidancesign Manufacturer Inc
 108 Fairgrounds Dr. Suite 8
 Manlius, NY 13104

**AIRPORT LIGHTING
 EQUIPMENT
 CERTIFICATION PROGRAM**

**CERTIFICATE OF
 CONFORMANCE**

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. The certification is not valid for a product modified with non-OEM replacements parts or non-production components.

L-858 – Signs, Runway and Taxiway (AC 150/5345-44J)						
Manufacturer	Type	Size	Style	Class	Mode	Manufacturer's Catalog Number
AGM Airfield	Y, R, L	1	2	1, 2	2	I12GX.XXF (231)
Guidancesign	Y, R, L	2	2	1, 2	2	I22GX.XXF (231)
Manufacturers	Y, R, L	3	2	1, 2	2	I32GX.XXF (231)
Inc.	B	4	2	1, 2	2	I42G1.0XF (231)
	B, H	5	2	1, 2	2	I52G1.0XF (231)
	Y, R, L	1, 2, 3	4	2	2	I14NX.XXF; I24NX.XXF; I34NX.XXF

1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.
2. Product tested and Report issued by: Intertek, AGM

(A) Report No: I-LUX62111; 100168890CRT-001;
 100414867CRT-001; UPDATE REPORT 11/4/13;
 2-13-14AGM

(B) Date of Report: 6/2011; 7/2010; 5/2011; 11/2013;
 2/2014

NOTE: PLEASE REVIEW, AND ADVISE
 ADMINISTRATOR AT INTERTEK IMMEDIATELY
 IF DATA, AS SHOWN, NEED TO BE
 CORRECTED.

Approved for Certification by:

Jeremy N. Downs, P.E., Program Administrator
 Date: May 14, 2014