



Intertek

PROGRAM ADMINISTRATOR
DEPARTMENT ALECP
INTERTEK
3933 U.S. ROUTE 11
CORTLAND, NY 13045-0950

REVISION DATE: June 13, 2014

ORIGINAL ISSUE DATE: May 25, 2011

Recertification due: October 2018

An Activity Sponsored and Administered by Intertek

HALI-BRITE INC
PO Box 10
925 1st St. SW
Crosby, MN 56441

**AIRPORT LIGHTING
EQUIPMENT
CERTIFICATION PROGRAM**

**CERTIFICATE OF
CONFORMANCE**

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. This Certificate is only confirmable in conjunction with equipment being listed in AC 150/5345-53, Appendix 3, Addendum, as currently published by the FAA. The certification is not valid for a product modified with non-OEM replacements parts or non-production components.

L-806(L) – Wind Cones, Frangible (AC 150/5345-27E)				
Manufacturer	Size	Manufacturer's Catalog Number		
		Lighted		Unlighted
		Style 1A External	Style 1B Internal	
Hali-Brite Inc.	1	L806-S1-EX-120-ON-5 (427)	L-806-S1-IN-120-ON-5 (601)	L806-S1-UN-NON-ON-N
	1	L806-S1-EX-66A-ON-5 (429)	L-806-S1-IN-66A-ON-5 (602)	
	1	L806-S1-EX-120-ON-N (226)		
	1	L806-S1-EX-12-ON-5 (428)		

NOTE: (601) 9200-0038 LED 120VAC; (602) 9200-0039 LED 6.6A

Equipment meets the requirements of FAA Engineering Brief No. 67D additional requirements for "Light Sources Other Than Incandescent and Xenon for Airport and Obstruction Lighting Fixtures" dated March 6, 2012

1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.
2. Product tested and Report issued by: Intertek; ICSI

(A) Report No: 100221131CRT-001;
100221131MIN-004; 100308988CRT-001;
100308988MIN-008; 100968915CRT-001; 200613;
101615143CRT-001

(B) Date of Report: 10/2010; 11/2010; 3/2011;
5/2011; 10/2013; 6/2013; 6/2013; 5/2014

NOTE: PLEASE REVIEW, AND ADVISE ADMINISTRATOR AT INTERTEK IMMEDIATELY IF DATA, AS SHOWN, NEED TO BE CORRECTED.

Approved for Certification by:

Jeremy N. Downs, P.E., Program Administrator
Date: June 13, 2014