



ORIGINAL ISSUE DATE: February 20, 2009

PROGRAM ADMINISTRATOR
DEPARTMENT ALECP
INTERTEK
3933 U.S. ROUTE 11
CORTLAND, NY 13045-0950

Recertification due: February 2015

An Activity Sponsored and Administered by
Intertek

ATG AIRPORTS LTD.
Automation House
Lowton Business Park
New Road
Lowton St. Mary's, Warrington UK WA3 2AP

**AIRPORT LIGHTING
EQUIPMENT
CERTIFICATION PROGRAM**

**CERTIFICATE OF
CONFORMANCE**

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. The certification is not valid for a product modified with non-OEM replacement parts or non-production components.

L-850 – Lights, Runway, Inpavement (AC 150/5345-46C)				
Manufacturer	Type	Class	Style	Manufacturer's Catalog Number
ATG Airports Ltd.	A	1, 2	2	ZA484-WW-X (126); ZA484-WR-X (126)
	A	1, 2	2	ZA484-W-X (126); ZA484-R-X (126)
	B	1, 2	2	ZA480-W-X (126)
	C	1, 2	2	ZA483-WW-X (160); ZA483-WY-X (160);
	C	1, 2	2	ZA483-WR-X (160); ZA483-YR (160); ZA483-YG-X (160)
	D	1, 2	2	ZA488-GR-X (160); ZA488-RR-X (160); ZA488-G-X (160)
	E	1, 2	2	ZA485-G-X (160)

1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.
2. Product tested and Report issued by: Intertek; ATG Airports Ltd.

(A) Report No: WT5/DK0606/480-1REV; (B) Date of Report: 2/2008; 2/2008; 4/2008
3139028CRT-001; 3149168CRT-001

NOTE: PLEASE REVIEW, AND ADVISE ADMINISTRATOR AT INTERTEK IMMEDIATELY IF DATA, AS SHOWN, NEED TO BE CORRECTED.

Approved for Certification by:

Jeremy N Downs, PE, Program Administrator
Date: February 20, 2009